

	A	B	C	D	E	F
1	<b>Lac LaBelle</b>					
2		(feet)				
3	Summer Level	2.00	86.00	851.83	March 15	Slow/No Wake Goes On At 2.67 (8" above)
4	Winter Level	1.00	85.00	850.83	November 1	Slow/No Wake Goes Off At 2.50 (6" above)
5	Gauge Bottom	0.00	84.00	849.83		
6			<b>Bench</b>	<b>MSL</b>	<b>Inches</b>	
7	<b>Date</b>	<b>Reading</b>	<b>Mark</b>	<b>Elevation</b>	<b>Above/Below</b>	<b>Actions</b>
8			<b>Elevation</b>		<b>Normal</b>	
9	<b>2023</b>					
10						
11	1/1/2023					
12	1/2/2023					
13	1/3/2023	1.70	85.70	851.53	8.4	
14	1/4/2023	1.70	85.70	851.53	8.4	
15	1/5/2023	1.70	85.70	851.53	8.4	
16	1/6/2023	1.68	85.68	851.51	8.16	
17	1/7/2023					
18	1/8/2023					
19	1/9/2023	1.40	85.40	851.23	4.8	
20	1/10/2023	1.40	85.40	851.23	4.8	
21	1/11/2023	1.36	85.36	851.19	4.32	
22	1/12/2023	1.36	85.36	851.19	4.32	
23	1/13/2023					
24	1/14/2023					
25	1/15/2023					
26	1/16/2023	1.18	85.18	851.01	2.16	
27	1/17/2023	1.18	85.18	851.01	2.16	
28	1/18/2023	1.20	85.20	851.03	2.4	
29	1/19/2023	1.20	85.20	851.03	2.4	
30	1/20/2023	1.20	85.20	851.03	2.4	
31	1/21/2023					
32	1/22/2023					
33	1/23/2023	1.22	85.22	851.05	2.64	
34	1/24/2023	1.24	85.24	851.07	2.88	
35	1/25/2023	1.24	85.24	851.07	2.88	
36	1/26/2023					
37	1/27/2023					
38	1/28/2023					
39	1/29/2023					
40	1/30/2023	1.36	85.36	851.19	4.32	
41	1/31/2023	1.36	85.36	851.19	4.32	
42	2/1/2023	1.36	85.36	851.19	4.32	
43	2/2/2023	1.36	85.36	851.19	4.32	
44	2/3/2023	1.36	85.36	851.19	4.32	
45	2/4/2023					
46	2/5/2023					
47	2/6/2023	1.36	85.36	851.19	4.32	
48	2/7/2023	1.36	85.36	851.19	4.32	
49	2/8/2023	1.36	85.36	851.19	4.32	
50	2/9/2023	1.40	85.40	851.23	4.8	
51	2/10/2023	1.40	85.40	851.23	4.8	
52	2/11/2023					
53	2/12/2023					
54	2/13/2023	1.38	85.38	851.21	4.56	
55	2/14/2023	1.38	85.38	851.21	4.56	
56	2/15/2023	1.36	85.36	851.19	4.32	
57	2/16/2023	1.34	85.34	851.17	4.08	
58	2/17/2023	1.34	85.34	851.17	4.08	
59	2/18/2023					
60	2/19/2023					
61	2/20/2023	1.26	85.26	851.09	3.12	
62	2/21/2023	1.24	85.24	851.07	2.88	
63	2/22/2023	1.24	85.24	851.07	2.88	
64	2/23/2023	1.26	85.26	851.09	3.12	

	A	B	C	D	E	F
65	2/24/2023	1.30	85.30	851.13	3.6	
66	2/25/2023					
67	2/26/2023					
68	2/27/2023	1.42	85.42	851.25	5.04	
69	2/28/2023	1.44	85.44	851.27	5.28	
70	3/1/2023	1.48	85.48	851.31	5.76	
71	3/2/2023	1.48	85.48	851.31	5.76	
72	3/3/2023	1.50	85.50	851.33	6	
73	3/4/2023					
74	3/5/2023					
75	3/6/2023	1.56	85.56	851.39	6.72	
76	3/7/2023	1.56	85.56	851.39	6.72	
77	3/8/2023	1.56	85.56	851.39	6.72	
78	3/9/2023	1.60	85.60	851.43	7.2	
79	3/10/2023	1.70	85.70	851.53	8.4	
80	3/11/2023					
81	3/12/2023					
82	3/13/2023	1.80	85.80	851.63	9.6	
83	3/14/2023	1.86	85.86	851.69	10.32	
84	3/15/2023	2.00	86.00	851.83	0	
85	3/16/2023	2.10	86.10	851.93	1.2	
86	3/17/2023	2.12	86.12	851.95	1.44	
87	3/18/2023					
88	3/19/2023					
89	3/20/2023	2.08	86.08	851.91	0.96	
90	3/21/2023	1.98	85.98	851.81	-0.24	
91	3/22/2023	1.88	85.88	851.71	-1.44	
92	3/23/2023	1.70	85.70	851.53	-3.6	
93	3/24/2023					
94	3/25/2023					
95	3/26/2023					
96	3/27/2023	1.40	85.40	851.23	-7.2	Installed 4 rows bays 1-7
97	3/28/2023	1.42	85.42	851.25	-6.96	Removed row 3-4 bays 4,5
98	3/29/2023	1.60	85.60	851.43	-4.8	Installed row 3 in bays 4,5
99	3/30/2023	1.70	85.70	851.53	-3.6	
100	3/31/2023					
101	4/1/2023					
102	4/2/2023					
103	4/3/2023	2.54	86.54	852.37	6.48	Removed row 2,3,4 bay 2-6
104	4/4/2023	2.46	86.46	852.29	5.52	
105	4/5/2023	2.54	86.54	852.37	6.48	Removed all dam boards
106	4/6/2023	2.42	86.42	852.25	5.04	
107	4/7/2023					
108	4/8/2023					
109	4/9/2023					
110	4/10/2023	2.04	86.04	851.87	0.48	
111	4/11/2023	1.98	85.98	851.81	-0.24	
112	4/12/2023	1.90	85.90	851.73	-1.2	
113	4/13/2023	1.86	85.86	851.69	-1.68	Install all boards bay 1/7 row 1-3 bay 2-6
114	4/14/2023	2.00	86.00	851.83	0	
115	4/15/2023					
116	4/16/2023					
117	4/17/2023	2.34	86.34	852.17	4.08	Remove row 3 bay 3-5 / close carb gates
118	4/18/2023	2.28	86.28	852.11	3.36	
119	4/19/2023	2.24	86.24	852.07	2.88	
120	4/20/2023	2.28	86.28	852.11	3.36	
121	4/21/2023	2.24	86.24	852.07	2.88	
122	4/22/2023					
123	4/23/2023					
124	4/24/2023	2.16	86.16	851.99	1.92	Lots of carp in river water level high
125	4/25/2023	2.16	86.16	851.99	1.92	
126	4/26/2023	2.16	86.16	851.99	1.92	
127	4/27/2023	2.16	86.16	851.99	1.92	
128	4/28/2023	2.20	86.20	852.03	2.4	

	A	B	C	D	E	F
129	4/29/2023					
130	4/30/2023					
131	5/1/2023	2.28	86.28	852.11	3.36	Lots of carp in river water level high
132	5/2/2023	2.26	86.26	852.09	3.12	
133	5/3/2023	2.26	86.26	852.09	3.12	
134	5/4/2023	2.24	86.24	852.07	2.88	
135	5/5/2023	2.20	86.20	852.03	2.4	
136	5/6/2023					
137	5/7/2023					
138	5/8/2023	2.18	86.18	852.01	2.16	Less carp in river water level low
139	5/9/2023	2.14	86.14	851.97	1.68	
140	5/10/2023	2.14	86.14	851.97	1.68	
141	5/11/2023	2.12	86.12	851.95	1.44	
142	5/12/2023	2.10	86.10	851.93	1.2	
143	5/13/2023					
144	5/14/2023					
145	5/15/2023	2.08	86.08	851.91	0.96	Very few carp below dam but some in lake
146	5/16/2023	2.08	86.08	851.91	0.96	
147	5/17/2023	2.06	86.06	851.89	0.72	
148	5/18/2023	2.00	86.00	851.83	0	
149	5/19/2023	1.88	85.88	851.71	-1.44	Installed all dam boards except bay 4 row 4
150	5/20/2023					
151	5/21/2023					
152	5/22/2023	1.96	85.96	851.79	-0.48	No carp at dam
153	5/23/2023	2.00	86.00	851.83	0	
154	5/24/2023	2.20	86.20	852.03	2.4	
155	5/25/2023	2.28	86.28	852.11	3.36	1 board out bay 2-5
156	5/26/2023	2.26	86.26	852.09	3.12	
157	5/27/2023					
158	5/28/2023					
159	5/29/2023					
160	5/30/2023	2.20	86.20	852.03	2.4	
161	5/31/2023	2.18	86.18	852.01	2.16	
162	6/1/2023	2.18	86.18	852.01	2.16	
163	6/2/2023	2.18	86.18	852.01	2.16	20 carp behind dam trying to leave lake
164	6/3/2023					
165	6/4/2023					
166	6/5/2023	2.14	86.14	851.97	1.68	22 carp behind dam trying to leave lake
167	6/6/2023	2.14	86.14	851.97	1.68	
168	6/7/2023	2.18	86.18	852.01	2.16	No carp at dam
169	6/8/2023	2.16	86.16	851.99	1.92	Opening fish grates to let carp leave lake 10 carp leaving lake 1 turtle
170	6/9/2023	2.16	86.16	851.99	1.92	
171	6/10/2023					
172	6/11/2023					
173	6/12/2023	2.10	86.10	851.93	1.2	
174	6/13/2023	2.10	86.10	851.93	1.2	
175	6/14/2023	2.08	86.08	851.91	0.96	
176	6/15/2023	2.08	86.08	851.91	0.96	
177	6/16/2023	2.10	86.10	851.93	1.2	No carp at dam
178	6/17/2023					
179	6/18/2023					
180	6/19/2023	2.10	86.10	851.93	1.2	No carp at dam
181	6/20/2023	2.12	86.12	851.95	1.44	
182	6/21/2023	2.10	86.10	851.93	1.2	
183	6/22/2023	2.08	86.08	851.91	0.96	
184	6/23/2023	2.10	86.10	851.93	1.2	No carp at dam
185	6/24/2023					
186	6/25/2023					
187	6/26/2023	2.08	86.08	851.91	0.96	
188	6/27/2023	2.08	86.08	851.91	0.96	
189	6/28/2023	2.04	86.04	851.87	0.48	
190	6/29/2023	2.00	86.00	851.83	0	No carp at dam
191	6/30/2023	2.00	86.00	851.83	0	
192	7/1/2023					

	A	B	C	D	E	F
193	7/2/2023					
194	7/3/2023	2.00	86.00	851.83	0	No carp at dam
195	7/4/2023	2.00	86.00	851.83	0	
196	7/5/2023	2.00	86.00	851.83	0	
197	7/6/2023	2.00	86.00	851.83	0	
198	7/7/2023	2.00	86.00	851.83	0	
199	7/8/2023					
200	7/9/2023					
201	7/10/2023	2.00	86.00	851.83	0	
202	7/11/2023	2.00	86.00	851.83	0	
203	7/12/2023	2.00	86.00	851.83	0	
204	7/13/2023	2.08	86.08	851.91	0.96	
205	7/14/2023	2.08	86.08	851.91	0.96	No carp at dam
206	7/15/2023					
207	7/16/2023					
208	7/17/2023	2.00	86.00	851.83	0	No carp at dam
209	7/18/2023	2.00	86.00	851.83	0	
210	7/19/2023	2.00	86.00	851.83	0	
211	7/20/2023	2.00	86.00	851.83	0	
212	7/21/2023	2.00	86.00	851.83	0	No carp at dam
213	7/22/2023					
214	7/23/2023					
215	7/24/2023	2.00	86.00	851.83	0	
216	7/25/2023	1.98	85.98	851.81	-0.24	
217	7/26/2023	1.98	85.98	851.81	-0.24	
218	7/27/2023	1.98	85.98	851.81	-0.24	
219	7/28/2023	1.98	85.98	851.81	-0.24	No carp at dam
220	7/29/2023					
221	7/30/2023					
222	7/31/2023	2.02	86.02	851.85	0.24	
223	8/1/2023	2.02	86.02	851.85	0.24	
224	8/2/2023	2.04	86.04	851.87	0.48	
225	8/3/2023	2.04	86.04	851.87	0.48	
226	8/4/2023	2.02	86.02	851.85	0.24	No carp at dam
227	8/5/2023					
228	8/6/2023					
229	8/7/2023	2.00	86.00	851.83	0	
230	8/8/2023	2.00	86.00	851.83	0	
231	8/9/2023	1.98	85.98	851.81	-0.24	
232	8/10/2023	1.96	85.96	851.79	-0.48	
233	8/11/2023	1.94	85.94	851.77	-0.72	Installed all dam boards
234	8/12/2023					
235	8/13/2023					
236	8/14/2023	2.10	86.10	851.93	1.2	No carp at dam
237	8/15/2023	2.14	86.14	851.97	1.68	
238	8/16/2023	2.26	86.26	852.09	3.12	
239	8/17/2023	2.26	86.26	852.09	3.12	
240	8/18/2023	2.28	86.28	852.11	3.36	No carp at dam
241	8/19/2023					
242	8/20/2023					
243	8/21/2023	2.24	86.24	852.07	2.88	few carp at dam below, will monitor movemen
244	8/22/2023	2.24	86.24	852.07	2.88	
245	8/23/2023	2.24	86.24	852.07	2.88	
246	8/24/2023	2.24	86.24	852.07	2.88	
247	8/25/2023	2.26	86.26	852.09	3.12	
248	8/26/2023					
249	8/27/2023					
250	8/28/2023	2.26	86.26	852.09	3.12	No carp at dam
251	8/29/2023	2.24	86.24	852.07	2.88	
252	8/30/2023	2.24	86.24	852.07	2.88	
253	8/31/2023	2.2	86.20	852.03	2.4	
254	9/1/2023	2.20	86.20	852.03	2.4	No carp at dam
255	9/2/2023					
256	9/3/2023					

	A	B	C	D	E	F
257	9/4/2023					
258	9/5/2023	2.18	86.18	852.01	2.16	No carp at dam
259	9/6/2023	2.18	86.18	852.01	2.16	
260	9/7/2023	2.18	86.18	852.01	2.16	
261	9/8/2023	2.18	86.18	852.01	2.16	
262	9/9/2023					
263	9/10/2023					
264	9/11/2023	2.14	86.14	851.97	1.68	No carp at dam
265	9/12/2023	2.14	86.14	851.97	1.68	
266	9/13/2023	2.14	86.14	851.97	1.68	
267	9/14/2023	2.16	86.16	851.99	1.92	
268	9/15/2023					
269	9/16/2023					
270	9/17/2023					
271	9/18/2023	2.18	86.18	852.01	2.16	No carp at dam
272	9/19/2023	2.18	86.18	852.01	2.16	
273	9/20/2023	2.16	86.16	851.99	1.92	
274	9/21/2023	2.16	86.16	851.99	1.92	
275	9/22/2023	2.16	86.16	851.99	1.92	
276	9/23/2023					
277	9/24/2023					
278	9/25/2023	2.20	86.20	852.03	2.4	
279	9/26/2023	2.20	86.20	852.03	2.4	
280	9/27/2023	2.34	86.34	852.17	4.08	
281	9/28/2023	2.40	86.40	852.23	4.8	Removed one row bay 2-6
282	9/29/2023	2.40	86.40	852.23	4.8	Removed row 2 bay 2-6
283	9/30/2023					
284	10/1/2023					
285	10/2/2023	2.00	86.00	851.83	0	No carp at dam
286	10/3/2023	1.90	85.90	851.73	-1.2	
287	10/4/2023	1.84	85.84	851.67	-1.92	Installed row 2 bay 2-6
288	10/5/2023	1.84	85.84	851.67	-1.92	Installed all boards but bay 4 row 1
289	10/6/2023	1.90	85.90	851.73	-1.2	
290	10/7/2023					
291	10/8/2023					
292	10/9/2023	1.90	85.90	851.73	-1.2	
293	10/10/2023	1.92	85.92	851.75	-0.96	
294	10/11/2023	1.92	85.92	851.75	-0.96	
295	10/12/2023	1.96	85.96	851.79	-0.48	
296	10/13/2023	2.00	86.00	851.83	0	
297	10/14/2023					
298	10/15/2023					
299	10/16/2023	2.40	86.40	852.23	4.8	Remove 2 rows bay 2-6
300	10/17/2023	2.22	86.22	852.05	2.64	No carp at dam
301	10/18/2023	2.10	86.10	851.93	1.2	
302	10/19/2023	2.00	86.00	851.83	0	
303	10/20/2023	1.90	85.90	851.73	-1.2	Install all boards except bay 4 row 4
304	10/21/2023					
305	10/22/2023					
306	10/23/2023	2.00	86.00	851.83	0	No carp at dam
307	10/24/2023	2.10	86.10	851.93	1.2	
308	10/25/2023	2.28	86.28	852.11	3.36	Removed 1 row bay 2-6
309	10/26/2023	2.26	86.26	852.09	3.12	
310	10/27/2023	2.28	86.28	852.11	3.36	Remove row 1 bay 1,7 row 2 bay 4,5
311	10/28/2023					
312	10/29/2023					
313	10/30/2023	2.00	86.00	851.83	0	
314	10/31/2023	2.04	86.04	851.87	0.48	
315	11/1/2023	2.08	86.08	851.91	0.96	
316	11/2/2023	2.06	86.06	851.89	0.72	
317	11/3/2023	2.04	86.04	851.87	0.48	Remove all of row 2
318	11/4/2023					
319	11/5/2023					
320	11/6/2023	1.86	85.86	851.69	-1.68	

	A	B	C	D	E	F
321	11/7/2023	1.80	85.80	851.63	-2.4	
322	11/8/2023	1.70	85.70	851.53	-3.6	
323	11/9/2023	1.68	85.68	851.51	-3.84	Removed all or row 3
324	11/10/2023	1.60	85.60	851.43	-4.8	
325	11/11/2023					
326	11/12/2023					
327	11/13/2023	1.54	85.54	851.37	-5.52	
328	11/14/2023	1.44	85.44	851.27	-6.72	
329	11/15/2023	1.40	85.40	851.23	-7.2	Removed all of row 4
330	11/16/2023	1.36	85.36	851.19	-7.68	
331	11/17/2023	1.28	85.28	851.11	-8.64	